



Product handbook

Grooving

— ENGINEERING KOMPETENZ

## Grooving applications with expertise



## Your guide for demanding grooving applications

With this practical handbook on grooving, we want to provide you with an aid which can offer you further assistance in a range of issues.

- Which tool should I use and when?
- Which chip formation should I choose?
- Which material can I machine, with which parameters – and, most importantly, using which machining strategy?

The handbook presents an overview of the various types of chip formation and of grades, systems and strategies. This is accompanied by important information about cutting data, application examples, solutions for difficult applications, as well as tips and tricks.

Perfect for planning and practical everyday use. All this and much more besides makes this handbook the ideal guide and problem-solver for the demanding area of grooving operations.



## CONTENTS

---

### **Grooving – Overview**

Grooving tools at a glance	2
Cutting tool materials	6
Geometry overview	8
Walter GPS	14

---

### **Grooving and parting off**

Tools for grooving and parting off	
incl. application examples	16
Walter Select for tools	22
Walter Select for cutting inserts	24
Application information	27
Walter Xpress	38

### **Recessing**

Tools for recessing	
incl. application examples	40
Walter Select for tools	42
Walter Select for cutting inserts	44
Application information	47

---

### **Axial grooving**

Tools for axial grooving	
incl. application examples	56
Walter Select for tools	58
Walter Select for cutting inserts	60
Application information	64

### **Internal grooving**

Tools for internal grooving	
incl. application examples	68
Walter Select for tools	70
Walter Select for cutting inserts	72
Application information	76

---


### **General information**


Precision cooling system overview	78
Geometry overview	82
Cutting tool material application chart	88
Cutting data	90
Wear analysis	94
Hardness comparison table	96

## Grooving tools at a glance

Grooving, parting off, internal recessing – axially and radially, for highly diverse workpiece materials and for a wide range of component profiles: There are recessing tools for an almost infinite array of operations.


Here are the most important systems together with their specific cutting inserts, shank shapes and cutting edge orientation at a glance.





## Walter Cut grooving systems by diameter range

Three systems – up to 200 mm




### Small parting off diameters of up to 12 mm

- Four-edged MX indexable inserts
- For economic grooving and parting off in mass production, as well as grooving special profiles



### Medium parting off diameters of up to 65 mm

- Double-edged GX/DX indexable inserts
- Method for grooving, parting off and recessing universally and efficiently




### Large parting off diameters of up to 200 mm

- Single-edged SX indexable inserts
- Inserts with self-clamping system, ideal for deep grooving and slot milling



## Cutting inserts



### Grooving and parting off

	<b>MX</b>	MX grooving inserts, four cutting edges
	<b>DX</b>	DX grooving inserts, two cutting edges
	<b>GX . . E</b>	GX grooving inserts, two cutting edges (E), one cutting edge (F)
	<b>GX . . F</b>	
	<b>SX</b>	SX grooving inserts, one cutting edge
	<b>UX</b>	UX grooving inserts, one cutting edge

### Recessing

	<b>GX</b>	GX grooving inserts, two cutting edges
---	-----------	---

### Semi-finished products/blanks

	<b>MX</b>	MX grooving inserts, four cutting edges
	<b>GX</b>	GX grooving inserts, two cutting edges
	<b>SX</b>	SX grooving inserts, one cutting edge

## Cutting tool materials

Heat-resistant and tough, the Tiger-tec® Silver grades with PVD  $\text{Al}_2\text{O}_3$  coating offer a very long tool edge life and process reliability.

### The Tiger-tec® Silver PVD grades for parting off, grooving and longitudinal turning

#### WSM13S

- For finishing and medium machining with uninterrupted cuts

#### WSM23S

- For stable conditions, high cutting speeds and when oil is used as the cooling lubricant


#### WSM33S

- First choice for steels, stainless steels and heat-resistant super alloys
- Outstanding wear resistance and high toughness

#### WSM43S

- Tough and reliable for steels, stainless steels and heat-resistant super alloys
- For interrupted cuts, low cutting speeds and unstable clamping or poor machine conditions

PDF – first choice for parting off



P M S

Wide range of applications – ISO

01 10 20 30 40  
05 15 25 35 45

Wear resistance

Toughness


good medium unfavourable

### PDF – $\text{Al}_2\text{O}_3$ heat shield for maximum wear resistance

#### COMPARISON

Heat ingress into carbide

#### Competitors



High level of heat ingress into carbide

#### Tiger-tec® Silver PVD



Thermal protection by  $\text{Al}_2\text{O}_3$

Tiger-tec® Silver CVD grades improve tool life quantity and productivity thanks to high hot hardness.

## The Tiger-tec® Silver CVD grades for grooving and longitudinal turning

### WKP13S

- Excellent wear resistance and high cutting speeds
- Continuous cutting


### WKP23S

- First choice for continuous cutting to slightly interrupted cuts
- High wear resistance and cutting speed


### WKP33S

- For excellent wear resistance and toughness
- For unfavourable conditions or interrupted cuts


CVD – first choice for recessing




### Wide range of applications – ISO



## CVD – coating and post-treatment for maximum toughness



Tensile stresses/risk of fractures in the CVD coating




Compressive stresses in the CVD coating caused by mechanical post-treatment

## Indexable insert geometries

The end of the designation key describes the cutting edge geometry:

<b>G</b>	<b>X</b>	<b>24</b>	–	<b>2</b>	<b>E</b>	<b>300</b>	<b>N</b>	<b>03</b>	–	<b>U</b>	<b>F</b>	<b>4</b>
1	2			3	4	5	6	7		8	9	10



## 8 – Application



**C "Cut off"**

- Parting off
- Radial grooving




**R "Radius"**

- Copy turning
- Radial grooving
- Axial grooving
- Longitudinal turning
- Facing



**G "Grooving"**

- Radial grooving
- Axial grooving
- Parting off



**U "Universal"**

- Longitudinal turning
- Radial grooving
- Axial grooving
- Facing
- Parting off

## 9 – Rake angle

smaller



A

larger



D



F



K

## 10 – Cutting edge

stable

sharp

1

3

4

6

8


## Geometries for parting off

The function of the chip formation is to guarantee optimal chip evacuation through chip constriction.

Chip formation for excellent chip constriction



3.00 mm



Chip constriction with the example of a CE4 geometry, material 42CrMo4, f: 0.12 mm.

Insert width = 3.00 mm  
Chip width = 2.95 mm

### CF6 – The sharp one

- Extremely low burr and pip formation
- For small diameters and thin-walled tubes

### CF5 – The positive universal one

- Low burr and pip formation
- For long-chipping materials

### CE4 – The universal stable one


- Stable cutting edge for maximum feeds
- Very good chip constriction

View  
Main cutting edge:  
Curved




Example: CF5

### COMPARISON OF PARTING OFF GEOMETRIES



## Geometries for grooving

A "straight" cutting edge is required to achieve the requisite flat groove base.



### GD8

- For precision grooving
- Light to moderate feeds

View  
Main cutting edge:  
Straight



Example: GD8


### GD3

- Light to moderate feeds
- General parting off and grooving operations

### GD6


- For long-chipping materials
- Moderate machining conditions

## COMPARISON OF GROOVING GEOMETRIES



## Geometries for recessing

Lateral chip formation for universal use in longitudinal turning.



### UF8

- Excellent chip control by means of a cutting edge with circumference fully ground
- Low to moderate feeds

#### View

Main cutting edge:



Example: UF8

### UF4

- Moderate feeds
- Universal insert for 80% of all applications


### UD4

- Excellent chip breaking on forged parts
- Stable cutting edge

### UA4


- For machining cast iron
- Moderate to high feeds

## COMPARISON OF RECESSING GEOMETRIES



## Geometries for copy turning

Indexable inserts for copy turning provide opportunities for efficiency when machining complex workpiece shapes.



Double geometry –  
good chip breaking  
for grooving and  
copy turning

Stable cutting edge  
for long tool life and  
process reliability

### RK8

- For copy and relief turning of ISO N materials
- Ground and polished cutting edge

#### View

Main cutting edge:



Example: RF8

### RF8

- For copy and relief turning
- Reduced cutting forces due to positive cutting edge with fully ground circumference

### RD4

- For copy turning, e.g. of forged parts
- Excellent chip control even at low depths of cut

## COMPARISON OF COPY TURNING GEOMETRIES



## Walter GPS – the fast and efficient way to the right application solution

Are you looking for the optimal machining solution for a particular application – be it milling, holemaking, threading or turning operations? With the Walter GPS machining navigation system, it takes just a few steps for you to find the right combination of tool, cutting data and machining strategy. Individually adapted to suit your material and your component.

PC, smartphone, tablet ...

Use Walter GPS online on a device and operating system of your choosing.

Based on all the information on every tool by Walter, Walter Titex and Walter Prototyp, Walter GPS selects one or more application recommendations for you – including a tool and the specific cutting data for your material.



### With Walter GPS, you will receive:

- Tool and cutting data recommendations perfectly adapted to suit your machining task
- Information about the machining strategy
- Tool costs and tool life for your machining
- Cost-efficiency calculations
- Detailed reports for documentation purposes

You can find Walter GPS at: [walter-tools.com](http://walter-tools.com)


## Walter GPS for grooving applications

### What to do:

Open up Walter GPS and click on your required type of search using the application. The material and the task must now be selected (here: Turning).


Next, the details:

### 1. Select machining method



### 2. Enter the machining parameters

- Diameter
- Tool adaptor
- R/L version
- Optional: Cutting width




### 3. View the results



## Four cutting edges with precision cooling

### Walter Cut MX – G3011-P groove turning holder


- Stable tangential insert clamping for optimal force absorption
- Maximum indexing accuracy thanks to dowel pin location in insert seat




### THE TECHNOLOGY

User-friendly thanks to self-aligning tangential screw clamping.

#### Maximum change accuracy thanks to dowel pin location in insert seat



#### Maximum stability and precision



## THE APPLICATION

- Grooving and parting off with four cutting edges
- DIN 471 circlip grooves with the tolerance class H13
- Grooving operations where maximum stability is required (e.g. grooving on inclined surfaces)
- Special profiles with Walter Xpress
- Use G3051-P for grooving on close shoulders

## APPLICATION EXAMPLE


### Grooving in stainless steel – Connector

**Material:** X2CrNiMo17-12-2 (1.4404)

**Tool:** G3011-C3R-MX22-2-P


**Indexable insert:** MX22-2E200N02-CF5

**Grade:** WSM23S



Cutting data:	Competitors Five-edged grooving insert	Walter Four-edged grooving insert
$v_c$ [m/min]	75	75
$f$ [mm]	0.05	0.07
Insert width [mm]	2.0	2.0
Cutting depth [mm]	2.5	2.5
Tool life quantity [units]	2.000	5.000


### Comparison: Tool life quantity [units]



## Innovative parting off system with SmartLock

### Walter Cut DX – G4014 / G4014-P groove turning holder

- Grooving and parting off tool with precision cooling
- Screw clamping on the side for easy insert changeover
- New clamping method: 30% higher clamping forces compared to conventional tools on the market
- Innovative positive engagement at the rear insert locating surface
- Shank sizes: 10 × 10, 12 × 12, 16 × 16, 20 × 20 mm




### THE TECHNOLOGY



### INDEXABLE INSERT CHANGEOVER


Walter – SmartLock



It is possible to change the inserts in the machine



Competitors



No insert change-over possible in the machine – toolholder must be removed

## THE APPLICATION

- Automatic lathe and multi-spindle machines having up to 150 bar of coolant pressure
- Parting off with low burr and pip formation (by 6°, 7° and 15° angled parting off inserts)
- Grooving and parting off along the main or counter-spindle up to dia. 35 mm for flexible use
- For replaceable components (as tool operation can be modified)

## APPLICATION EXAMPLE


### Axis dia. 10 mm – Parting off

Material:	X8CrNiS18-9 (DIN 1.4305)
Tool:	G4014.1616R-2T17DX18-P
Indexable insert:	DX18-1E200N02-CF5
Grade:	WSM33S



Cutting data:	Competitors	Walter
$v_c$ [m/min]	G1011.1616R-2T15GX16-P GX16-1E200N02-CF5 WSM33S	G4014.1616R-2T17DX18-P DX18-1E200N02-CF5 WSM33S
$f$ [mm]	80	80
Insert width [mm]	0.12/0.05	0.12/0.05
Cutting depth [mm]	2.0	2.0
Tool life quantity [units]	5	5
Tool life quantity [units]	4.000	8.000


### Comparison: Tool life quantity [units]



## Universal use


### Walter Cut SX – G2042-P deep parting blade

- G2042..N-P parting blades with precision cooling
- Can be used universally, neutral design
- Grooving to a cutting depth of up to 100 mm
- Parting off to a diameter of up to 200 mm



### POSITIVE-LOCKING SX CLAMPING SYSTEM

High retaining forces as a result of the optimised top clamp



The user-friendly self-clamping system ensures fast replacement of the cutting edge. The cutting forces are absorbed in the rigid section of the tool, rather than the flexible section of the tool.

The cutting insert is positively locked in the insert seat, therefore eliminating loss during withdrawal


## THE APPLICATION

Lathes of all types, in particular:

- Automatic lathes
- Multi-spindle machines
- Bar feed lathes
- Grooving and parting off along the primary or counter-spindle without interference contour

## APPLICATION EXAMPLE

### Parting off in stainless steel – Connector



**Material:** X6CrNiMoTi17-12-2 (1.4571)


**Tool:** G2042.32N-3T50SX-P

**Indexable insert:** SX-3E300N02-CE4 WSM33S

**Grade:** WSM33S



Cutting data:	Competitors	Walter
	XLCFN3203M31-FX	G2042.32N-3T50SX-P
	FX3.1-E310N015-CE4 WSM33	SX-3E300N02-CE4 WSM33S
<b>v<sub>c</sub> [m/min]</b>	120	120
<b>f [mm]</b>	0.04	0.1
<b>Insert width [mm]</b>	3.1	3.0
<b>Cutting depth [mm]</b>	12	12
<b>Tool life quantity [units]</b>	70	250

### Comparison: Tool life quantity [units]






# Walter Select – Groove turning holders and parting blades


## External machining – Radial

Application								
Space restrictions on the machine								
Stability of the tool								
Tools								
Designation		G3011-P G3011-C....P G3021-P G3051-P	G4014 G4014-P	G1011 G1011-P	G2012 G2012-P			
Max. parting off diameter $D_{max}$ [mm]	Max. cutting depth $T_{max}$ [mm]							
dia. 8	4	••	••	••	••			
dia. 10	5	••	••	••	••			
dia. 12	6	••	••	••	••			
dia. 16	8		••	••	••			
dia. 24	12		••	••	••			
dia. 35	18		••	••	••			
dia. 42	21			••	••			
dia. 52	26			••	••			
dia. 65	33			••	••			
dia. 80	40				••			
dia. 90	45				••			
dia. 120	60				••			
dia. 200	100							
Insert width $s$ [mm]	0.5–5.56	1.5–3.0	2.0–8.0	1.5–10.0				
Shank height $h$ [mm]	10–25	10–20	12–32	12–32				
Blade height $h_4$ [mm]	–	–	–	–				
Walter Capto™ size $d_1$	C3–C6	–	–	–				
Cutting insert type		MX ...		DX ...		GX ...		SX ...

 -P = Precision cooling (first choice)



- Deep grooves
- Long tool/counter-spindle overhang



-

-

+

-

G2612  
G2622

G2016-P

G1041R/L  
G1041R/L-P

G1042N

G2042R/L  
G2042R/L-PG2042N  
G2042N-P

••

••

••

••

••

••

••

••

••

••

••

••

••

••

••

••

••

••

••

••

••

••

••

••

••

••

••

••

••

••

••

••

••

••

••

••

••

••

••

••

••

••

••

••

••

••

••

••

1.5-8.0

12-19

1.5-4.0

3.0-6.0

2.0-4.0

2.0-10.0

20-25

25-32

-

-

-

-

-

-

26-32

26-32

26-32

26-52

C3-C6

-

-

-

-


-



SX...



UX...



GX...E



GX...F



SX...

# Walter Select for cutting inserts for grooving and parting off

Step by step to the right cutting insert


## STEP 1

Determine the **material** to be machined.

Code letters	Machin- ing groups	Groups of the materials to be machined	
<b>P</b>	P1-P15	Steel	All types of steel and steel casting, with the exception of steel with an austenitic structure
<b>M</b>	M1-M3	Stainless steel	Austenitic stainless steel, austenitic-ferritic steel and steel casting
<b>K</b>	K1-K7	Cast iron	Grey cast iron, cast iron with spheroidal graphite, malleable cast iron, cast iron with vermicular graphite
<b>N</b>	N1-N10	NF metals	Aluminium and other non-ferrous metals, non-ferrous materials
<b>S</b>	S1-S10	High-temperature alloys and titanium alloys	Heat-resistant special alloys based on iron, nickel and cobalt, titanium and titanium alloys
<b>H</b>	H1-H4	Hard materials	Hardened steel, hardened cast iron materials, chilled cast iron
<b>O</b>	O1-O6	Other	Plastics, glass and carbon-fibre, reinforced plastics, graphite

## STEP 2


Determine the **basic shape** of the cutting insert:

multiple cutting edges	double-sided	single-sided
 MX...	 GX...E...  DX...E...	 SX...  GX...F...
-	Parting off diameter [D]	+
-	Cutting depth [T]	+



## STEP 3 – PARTING OFF

Determine the **cutting insert geometry** via the cutting edge stability and feed.



## STEP 4 – PARTING OFF

Check whether your chosen geometry is available in the required insert width [s]. Identify the available system.





Chip formation					
Insert width s [mm]	MX...	DX...E	GX...E	GX...F	SX...
CK8	–	–	2.0–4.0	–	2.0–6.0
GD8 <sup>1)</sup>	1.0–3.25	–	–	–	–
CF6	–	1.5–3.0	1.5–3.0	3.0	1.5–3.0
GD3 <sup>1)</sup>	–	–	2.0–6.0	–	–
CF5	0.8–5.56	1.5–3.0	1.5–5.0	3.0–5.0	1.5–6.0
GD6 <sup>1)</sup>	–	2.0–3.0	2.0–6.0	–	–
CE4	–	1.5–3.0	1.5–6.0	3.0–4.0	1.5–10.0
F1 <sup>2)</sup>	–	–	–	2.0–6.0	–

<sup>1)</sup> These grooving geometries are suitable for both parting off and grooving.

<sup>2)</sup> Laser-generated PCD chip geometry

## STEP 3 – GROOVING

Determine the **cutting insert geometry** via the cutting edge stability and feed.



## STEP 4 – GROOVING

Check whether your chosen geometry is available in the required insert width [s]. Identify the available system.

Chip formation	MX...	DX...E	GX...E	GX...F	SX...
Insert width s [mm]					
GD8 <sup>1)</sup>	1.0–3.25	–	1.0–1.4	–	–
GD3 <sup>1)</sup>	–	–	2.0–6.0	–	–
GD6 <sup>1)</sup>	–	1.5–3.0	2.0–6.0	–	–
CE4 <sup>1)</sup>	–	–	1.5–6.0	3.0–4.0	1.5–10.0
UF8	–	–	1.7–8.0	–	–
UF4	–	–	2.0–8.0	–	8.0
UD4	–	–	2.0–8.0	–	–
F1 <sup>2)</sup>	–	–	–	2.0–6.0	–

<sup>1)</sup> These grooving geometries are suitable for both parting off and grooving.

<sup>2)</sup> Laser-generated PCD chip geometry

## Application information – Parting off

### As a general rule:

The most stable tool possible for parting off should always be selected. This prevents vibration and increases the tool life.

### Insert width

The insert width selected should be as narrow as possible, but as wide as necessary.

Reducing the insert width reduces the cutting force and saves material.




### Cutting depth

1. The max. cutting depth [ $T_{max}$ ] of the tool and the max. clamping length of the insert holder should not exceed  $10 \times$  the insert width [s].

The smallest possible cutting depth should always be selected.



2. If the maximum cutting depth does not exceed the second cutting edge, double-edged Walter Cut GX or DX indexable inserts are the most efficient option. If the cutting depth is greater, single-edged Walter Cut SX cutting inserts are the first choice.



## Application information – Parting off

### Use a neutral cutting edge for:

- Improved chip formation
- Lower resultant cutting forces
- Longer tool life

The design of the cutting inserts (right/left) can be determined by viewing the cutting edge from above where the parting off pip remains, unlike the tools, which are instead viewed from the front.

**1st choice**



Neutral



Right




Left


**Tip:** In general, the following rules apply.

#### Direction of rotation of the machine spindle:


Clockwise → right cutting insert  
Anticlockwise → left cutting insert



Above the centre



Centre



Under the centre

### Checking the centre height [f]

- Longer/more consistent tool life
- Reduced pip/burr formation

If the tool is positioned over or under centre, the effective cutting angles change during machining.

### Reducing the feed

From a diameter of  $1.5 \times s$  [mm], reduce the feed [f] by approx. 50–75%.

Do not groove past the centre, as this creates a risk of fracture.

It is possible to groove past the centre to a maximum of corner radius  $+0.1$  mm.\*

For any further, a constant cutting speed and speed limitation should be used. This is based on the clamping unit and/or bar loader.



\* Programming note:  
With a corner radius of 0.3 mm, the x measurement should be adjusted in the direction of -0.4 mm.



#### Smaller corner radius

- Smaller pips
- Better chip control
- Lower feed



#### Larger corner radius

- Higher feed
- Longer tool life

---

#### Use the largest tool possible – in relation to the height of the support [h]


- Greater tool rigidity
- Lower vibration
- Longer tool life




---

#### Use the smallest insert width possible

- Lower cutting force
- Reduced material consumption




---


#### Clamp the workpiece at the shortest length possible and part off as close to the spindle as possible



## Application information – Parting off


### Mount the tool in the machine with the shortest possible overhang

- Better face flatness
- Reduced vibration tendency
- Longer tool life




### Retracting the tool

After parting off, do not retract the tool immediately. First, step off axially and then retract.



### Chamfering and parting off



1. Pre-grooving

2. Chamfering

3. Parting off


### Internal chamfering before parting off

The peripheral cutting edges of the chamfering tool and parting off tool must be precisely aligned to achieve the most burr-free result possible.




### Parting off to a bore

The bore must be pre-drilled to be deep enough for the entire cutting edge width of the parting off tool to exit in the cylindrical section of the bore.



### The tool must be aligned 90° to the axis of rotation

- Better face flatness
- Reduced vibration tendency



### Precision cooling when parting off

Integrated precision cooling cools both the rake and flank faces exactly where it is needed. Combined with **Tiger-tec® Silver** indexable inserts, the tool demonstrates a two- to four-fold increase in tool life for parting off operations.


Vibration, chip jams and tool breakage, which would normally be a common occurrence given less than optimal conditions, are now a thing of the past. A higher quality surface finish is another of the benefits of this new design.



## Application information – Parting off


### Tool use

- Use the tool holder with the smallest possible cutting depth ( $T_{max}$ ) for the application.



### Cutting insert change

- When changing the cutting inserts, ensure that the new cutting insert lies securely against the tool holder stop.
- Before inserting the cutting insert, it is important to check to ensure that the insert seat is free from dirt and damage.
- Insert the cutting insert along the prismatic surfaces and into the insert seat, and watch out for resistance.
- Never tighten the clamping screw if there is no cutting insert in the insert seat.  
Tighten the clamping screw to the recommended torques.



Tool	Tightening torque
G15..	5.0 Nm
G1011	5.0 Nm
G1111	4.0 Nm
G1221	4.0 Nm
G1041	3.5 Nm
G30..	5.0 Nm
G4014	$\leq 12 \text{ mm}$ 2.0 Nm
G4014	$\geq 12 \text{ mm}$ 3.0 Nm
XLDE	3.5 Nm

## Application information – Parting off with inclined cutting edges

When parting off solid material, the use of cutting inserts with lead angles reduces the formation of residual pips on the component that has been parted off.



Left-hand cutting insert:  
Pips on the bar



Neutral cutting insert:  
Pips on the workpiece



Right-hand cutting insert:  
Pips on the workpiece

When parting off tubular material, the use of inclined cutting inserts prevents rings from forming. These rings could otherwise remain on the parted off component and interfere with the rest of the manufacturing process. It also leads to reduced burr formation.




Left-hand cutting insert:  
Burr on the left of the tube



Neutral cutting insert:  
Burr on the right of the tube

When inclined cutting inserts are used for parting off, the lead angle is likely to be detrimental to chip formation. The chip rolls at  $90^\circ$  to the main cutting edge, preventing it from forming a watch spring shape (as with a neutral cutting insert), and instead causing it to form a helical shape.




### TIP:

One option for breaking the chamfer chip is to interrupt cutting briefly once a cutting depth of  $1-2 \times s$  is reached. Once cutting resumes, the chip flows in the existing groove and breaks.

## Application information – Parting off with inclined cutting edges


## TIP:

The feed values must be reduced by approximately 30% because the tool tends to run off-centre as a result of the axial force generated [ $F_n$ ]. This can lead to vibration and convex parted off surfaces.



## Effects on machining

Neutral cutting insert



Inclined cutting insert



Stability and tool life	✓ good	✗ poor
Radial cutting forces (positive)	✗ high	✓ low
Axial cutting forces (negative)	✓ low	✗ high
Residual pip/burr formation	✗ large	✓ small
Risk of vibration	✓ low	✗ high
Surface quality and flatness	✓ good	✗ poor
Chip flow	✓ good	✗ poor

The use of inclined cutting inserts always has a negative effect on the cutting insert tool life (see table).

If possible, neutral cutting inserts should be used.

This statement applies particularly for machines with counter-spindles.

## Application conditions – Reinforced blades


## “Overhead” installation position

Contra blade



Main spindle

Counter-spindle




G2042.32R-..T.. SX-C  
G1041.32R-..T.. GX-..C

## “Normal” installation position



Main spindle

Counter-spindle



G2042.32R-..T.. SX  
G1041.32R-..T.. GX..


## “Normal” installation position

Contra blade



Main spindle

Counter-spindle



G2042.32L-..T.. SX-C  
G1041.32L-..T.. GX-..C

## Fault analysis – Parting off

### Large residual pip/burr

- Reduce the feed value by 50–75% at a diameter of  $1.5 \times s$  or above ( $s$  = cutting edge width)
- Use a cutting insert with a lead angle
- Use a narrower insert (reduction of the cutting forces)
- Choose a smaller corner radius
- Choose a more positive geometry
- Check the centre height



### Poor surface/vibration

- Use a more stable tool
- Clamp the tool at a shorter length
- Check whether the insert seat is damaged
- Choose a more positive geometry
- Increase the feed



### Damage caused by chips

- Use a chip formation with greater chip constriction
- Reduce the cutting speed
- Use a straight cutting insert
- Optimise the cooling (use of precision cooling tools)
- Increase the feed



**Poor chip formation**


- Reduce the cutting speed
- Improve the cooling (use of precision cooling tools)
- Check the chip formation
- Increase the feed

**Poor face flatness**

- Use a cutting insert with as small a lead angle as possible or no lead angle at all
- Use a tool with the smallest possible cutting depth
- Reduce the feed for cutting inserts with a lead angle
- Choose a smaller corner radius
- Choose a more positive geometry
- Align the tool correctly

**Chip formation when parting off**

- Chip constriction inhibits friction on the side walls of the tool and reduces chip accumulation
- Enables higher feed values
- No damage to parted off surfaces
- Chips are rolled up helically and broken short, so that they can exit the groove with ease – "watch spring chip"
- Chip width measured at approx. 0.05–0.10 mm smaller than the insert width [s]



## Walter Xpress – Delivery service

### Custom solutions in next to no time

Walter offers a wide range of products that can be sourced through the Walter Xpress rapid delivery service: Tools – as well as indexable inserts (e.g. for turning and holemaking). The special custom solutions that you can order using this service just have to be "close to the standard tool".

The greatest advantage of Walter Xpress is the fact that delivery times are exceptionally short: Three weeks for indexable insert special tools and four weeks for indexable inserts.

Short replenishment times mean that Walter Xpress is crucial in contributing towards a reduction in the number of tools you have in circulation, consequently cutting your costs. You also benefit from a higher degree of certainty when planning.

#### Here's how to use Walter Xpress

Special tools available with Xpress delivery can be ordered via your Walter contact partner or via the online form in the Xpress area of the Walter website.

#### Benefits for you:

- Same-day grooving insert calculations incl. drawing
- Four-week delivery time
- Special widths and radii with CF5 / GD8 chip formation geometry
- Reduction of cost per part by reducing travel distances and multiple grooving


Find out more at:  
**walter-tools.com**

**Walter  Xpress**


## Special profiles in a four-week delivery time

### THE INDEXABLE INSERT

- Insert widths from 0.5–5.5 mm
- Cutting depths up to 6 mm
- Radii from 0.05–5.4 mm
- 3–20° approach angle
- 30–60° chamfer angle




### THE APPLICATION



Chamfering and grooving is normally carried out with the grooving insert's corner radii.

#### Disadvantages:

Long runtime and high wear on the peripheral cutting edges.



An Xpress special insert is recommended for chamfering and grooving in series production.


#### Advantages:

Shorter runtime and longer tool life, since wear is distributed across the entire cutting edge.

## Productive and universal



### Walter Cut GX – G1011 / G1011-P groove turning holder

- Monoblock tools for grooving, parting off and recessing
- G1011-P with precision cooling directly at the cutting edge increases the tool life and productivity
- For double-edged GX16-, GX24-, GX30- and GX34- grooving inserts
- Simple and more reliable chip evacuation thanks to reduced tool head height



### THE TECHNOLOGY

Optimum stability thanks to a selection of different cutting depths



1. Maximum clamping force due to optimum screw position
2. Clamping screw can be accessed from above or below


## THE APPLICATION

- Parting off, grooving and recessing operations up to a depth of 33 mm – double-edged.
- Double-edged parting off with GX34 to a diameter of up to 65 mm
- For use on lathes of all types
- First choice for all grooving/recessing operations

## APPLICATION EXAMPLE


### Recessing in steel – Gearbox cover

<b>Material:</b>	16MnCr5 (1.7131) $R_m = 1200 \text{ N/mm}^2$
<b>Tool:</b>	G1011.2525R-6T12GX24
<b>Indexable insert:</b>	GX24-4E600N08-UD4
<b>Grade:</b>	WKP33S





<b>Cutting data:</b>	<b>Competitors</b> N123L2-800-0008 TM4325	<b>Walter</b> G1011.2525R-6T12GX24 GX24-4E600N08-UD4 WKP33S
<b><math>v_c</math> [m/min]</b>	100	150
<b><math>f</math> [mm]</b>	0.1	0.2
<b><math>a_p</math> [mm]</b>	3.5	3.5
<b>Insert width [mm]</b>	8.0	6.0
<b>Tool life quantity [units]</b>	35	80

### Comparison: Tool life quantity [units]






# Walter Select – Groove turning holder for parting off/grooving/recessing

## External machining – Radial

Application					
Stability of the tool	+				
Tools					
Designation		G3011 G3011-C....P G3011-P G3051-P	G3021-P	G1011 G1011-P	G1511 G1511-P
Max. parting off diameter $D_{max}$ [mm]	Max. cutting depth $T_{max}$ [mm]				
dia. 8	4	••	••	••	••
dia. 10	5	••	••	••	••
dia. 12	6	••	••	••	••
dia. 16	8			••	
dia. 24	12			••	
dia. 32	16			••	
dia. 42	21			••	
dia. 52	26			••	
dia. 65	33			••	
dia. 80	40				
dia. 90	45				
dia. 120	60				
dia. 200	100				
Insert width s [mm]		0.5-5.56	0.5-5.56	2.0-8.0	1.0-6.0
Shank height h [mm]		10-25	10-25	12-32	12-25
Walter Capto™ size $d_1$		C3-C6	-	-	-
Cutting insert type			MX...E		GX...E
					GX...F

 -P = Precision cooling (first choice)



# Walter Select for cutting inserts for recessing

Step by step to the right cutting insert


## STEP 1

Determine the **material** to be machined.

Code letters	Machin- ing groups	Groups of the materials to be machined	
<b>P</b>	P1–P15	Steel	All types of steel and steel casting, with the exception of steel with an austenitic structure
<b>M</b>	M1–M3	Stainless steel	Austenitic stainless steel, austenitic-ferritic steel and steel casting
<b>K</b>	K1–K7	Cast iron	Grey cast iron, cast iron with spheroidal graphite, malleable cast iron, cast iron with vermicular graphite
<b>N</b>	N1–N10	NF metals	Aluminium and other non-ferrous metals, non-ferrous materials
<b>S</b>	S1–S10	High-temperature alloys and titanium alloys	Heat-resistant special alloys based on iron, nickel and cobalt, titanium and titanium alloys
<b>H</b>	H1–H4	Hard materials	Hardened steel, hardened cast iron materials, chilled cast iron
<b>O</b>	O1–O6	Other	Plastics, glass and carbon-fibre, reinforced plastics, graphite

## STEP 2


Determine the **basic shape** of the cutting insert:





### STEP 3 – RECESSING

Determine the **cutting insert geometry** via the cutting edge stability and feed.



### STEP 4 – RECESSING

Check whether your chosen geometry is available in the required insert width [s]. Identify the available system.

Chip formation				
Insert width s [mm]				
UF8	–	1.7–8.0	–	–
UD6	–	2.0–6.0	–	–
CF5 <sup>1)</sup>	0.8–5.56	–	–	–
UF4	–	2.0–8.0	–	8.0
UD4	–	2.0–8.0	–	–
UA4	–	2.0–6.0	–	–
F1 <sup>2)</sup>	–	–	2.0–6.0	–


<sup>1)</sup> Only for finishing operations with max.  $a_p = 0.3 \times s$

<sup>2)</sup> PCD cutting insert



## STEP 3 – COPY TURNING

Determine the **cutting insert geometry** via the cutting edge stability and feed.



## STEP 4 – COPY TURNING

Check whether your chosen geometry is available in the required insert width [s]. Identify the available system.


Chip formation				
Insert width s [mm]	MX...	GX...E	GX...F	SX...
RK8	-	6.0–8.0	-	-
RF8	-	2.0–8.0	-	-
RF5	1.57–5.0	-	-	-
RD4	-	2.0–8.0	-	-
M1 <sup>1)</sup>	-	-	2.0–8.0	-

<sup>1)</sup> PCD cutting insert

## Application information – Recessing


### General

The use of recessing tools allows machining steps to be grouped together, saving on the number of tools used – in particular for machining between shoulders or when a limited number of tool spaces are available.




### There are two different production strategies

For **grooving**, the feed moves in only one direction. Longitudinal turning with low material removal (approx. 0.1–0.3 mm) can only be carried out as a finishing operation. Grooving is effective when the groove depth is 1.5 times greater than the groove width.




**Recessing** is a combination of grooving and longitudinal turning movements. It is used when the groove width is 1.5 times greater than the groove depth.



### Positive engagement

A precise positive-locking connection between the cutting insert and the insert seat enables both radial and axial forces to be absorbed.

The longitudinal movement deflects the cutting insert [a].




## Application information – Recessing

### Deflection


Deflection means the deformation of the cutting insert support caused by a force  $[F_p]$ . This is necessary to create a minor clearance angle  $[\alpha]$  during longitudinal turning.

The following factors influence the degree of deflection:

- Depth of cut  $[a_p]$
- Feed  $[f]$
- Cutting speed  $[v_c]$
- Corner radius  $[r]$
- Material to be machined
- Cutting depth of the tool  $[T]$
- Width of the cutting insert support




This enables recessing and longitudinal turning operations when using special chip forming geometries. Universal geometries are ideally suited for use (e.g. UD4, UF4).



### Diameter compensation

The deflection produces different longitudinal ratios on the tool. In order to create an even diameter during a finishing operation, diameter compensation must take place when transitioning from the grooving movement to the longitudinal turning movement:

- ① Pre-machine the component up to the finishing operation
- ② Groove to the final diameter
- ③ Retract by 0.1 mm
- ④ Turn longitudinally
- ⑤ Measure the grooving diameter and longitudinal turning diameter; correct the retraction dimension (0.1 mm) by the difference in diameter




- ① Grooving  
( $a_p$  longitudinal turning movement)
- ② Retract by 0.1 mm

## Machining

Certain tool paths must be adhered to in order to ensure a reliable machining process: For example, a tool must not be subjected to strain in two directions at the same time. Therefore, the cutting edge must be relieved after grooving before you start the longitudinal turning operation – the same is true when moving from longitudinal turning into grooving operations.

### Rule of thumb – Recessing:

$f_{\text{start}}$	$0.05 \times s$
$f_{\text{max}}$	$0.07 \times s$
$a_p \text{ min}$	$r + 0.1 \text{ mm}$
$a_p \text{ max}$	$0.7 \times s$




### Machining sequence – Retracting


At the end of a longitudinal turning operation, retract by min. 0.1 mm:

In the opposite direction to the direction of feed and away from the machined diameter, such that the cutting edge returns to its original position and the next grooving operation can take place.

Before you transition to the longitudinal turning operation, retract by approx. 0.1 mm again.




### Producing a narrow groove with chamfer



## Application information – Recessing


## Producing a wide recess via multiple grooving




$s$  = cutting edge width /  $r$  = corner radius /  $a_p \text{ max}$  = max. depth of cut

## Producing a recess via recessing


## 1. Roughing



## 2. Finishing



① Pre-groove at the radius tangent point to the required finished diameter



② Finish the first shoulder and copy the radius  
 ③ Retract by the diameter compensation dimension

④ Turn longitudinally until the radius tangent point is reached  
 ⑤ Retract by 0.1 mm in two directions

⑥ Finish the second shoulder and copy the radius

## Surface quality

Recessing in comparison to ISO turning:

A "wiper effect" is generated by deflecting the cutting insert when recessing (see figure A).

**R<sub>a</sub> values under 0.5 µm are attainable. These result in a good load-bearing capacity.**




Fig. A





Fig. B

## Application information – Recessing

### Side offset [s] – [r]

For side offset grooving, a universal "U" geometry should be used. The insert width should be at least between  $0.5 \times s$  and the cutting edge width of  $s - 1 \times r$ .




$$a_p \text{ min: } 0.5 \times s$$

$$a_p \text{ max: } s - r$$


### Example:

$$s = 3.0 \text{ mm; } r = 0.2 \text{ mm} \rightarrow a_p \text{ min: } 1.5 \text{ mm}$$

$$a_p \text{ max: } 2.8 \text{ mm}$$



### Preventing ring formation




- ① Turn longitudinally up to approx. 0.5–1.5 mm in front of the tool exit
- ② Retract at an angle away from the corner

- ③ Position the tool above the ring
- ④ Remove the ring in the grooving operation


### The tool must be aligned 90° to the axis of rotation

This is the only way to ensure that a clearance angle can be created when the tool is turned in both directions. Poor tool alignment generates vibrations and can lead to tool breakage.



### Tool use


Use the tool holder with the smallest possible cutting depth ( $T_{\max}$ ) for the application.



## Application information – Copy turning

Cutting inserts for copy turning provide excellent opportunities for efficiency when machining complex workpiece shapes.

- Use cutting inserts for copy turning to achieve outstanding chip control and high surface finish quality
- With unstable clamping, ramp to avoid vibration



## Application information – Copy turning

### Preventing vibration during copy turning

- The radius of the indexable insert should always be smaller than the workpiece radius in order to avoid a large wrap (contact) angle.
- Reduce the feed in the workpiece radius range by 50% in comparison to the longitudinal cut.


Insert radius = workpiece radius

**Not recommended.**






Insert radius < workpiece radius

**Recommended.**




$f_{n1}$  = longitudinal cuts = max. chip thickness 0.15–0.40 mm

$f_{n2}$  = radius machining = 50% max. chip thickness



### Maximum $a_p$ when cutting with RD4 or RF8 geometries



Insert width s [mm]	$a_p$ max – RD4 [mm]	$a_p$ max – RF8 [mm]
2.0	0.10	0.10
3.0	0.20	0.25
4.0	0.30	0.20
5.0	0.35	0.25
6.0	0.45	0.30
8.0	0.70	0.35

## Fault analysis – Recessing

### Vibration during turning

- Check the tool alignment
- Deflection of the cutting insert is too low
- Use a narrower insert (deflects more sharply)
- Use a smaller corner radius
- Clamp the workpiece at a shorter length



### Step in turning diameter

- Correct the retraction dimension before the finishing cut
- Ensure even material removal
- Check whether the insert seat is damaged
- Increase the cutting speed
- Use a more positive geometry



### Damage caused by chips

- Use a chip formation with greater chip constriction
- Reduce the cutting speed
- Optimise the cooling (use of precision cooling tools)




### Ring formation

- Check the program sequence



### Poor chip formation


- Reduce the cutting speed
- Increase the feed
- Improve the cooling (use of precision cooling tools)
- Check the chip formation



## Highly reliable monoblock tool


### Walter Cut GX – G1111 groove turning holder

- Clamping screw can be accessed from above or below
- Two cutting depths available for optimum tool stability
- For excellent surfaces and tool edge life with maximum productivity



### THE TECHNOLOGY

#### Low tool head height enables good chip evacuation



#### Simple replacement of the cutting edge in overhead use



## THE APPLICATION

- Axial grooves from dia. 34 mm
- Cutting depths up to 25 mm
- Insert width from 3 mm
- For use on lathes of all types
- First choice for all axial grooving/recessing operations
- All GX24 chip formations can be used

## APPLICATION EXAMPLE


### Axial grooving in grey cast iron – Housing

**Material:** GG25 nitrided (EN-GJL-250)

**Tool:** G1111.2525R-4T12-064GX24


**Indexable insert:** GX24-3E400N04-UD4

**Grade:** WKP13S



Cutting data:	Competitors	Walter
	A4G0305M03U04GUP	G1111.2525R-4T12-064GX24
	KCP10	GX24-3E400N04-UD4 WKP13S
<b>n [rpm]</b>	350	350
<b>f [mm]</b>	0.05	0.08
<b>Insert width [mm]</b>	3.0	4.0
<b>Cutting depth [mm]</b>	4	4
<b>Tool life quantity [units]</b>	50	120

### Comparison: Tool life quantity [units]




## Axial grooving

# Walter Select – Groove turning holder for axial grooving and recessing

### External machining – Axial


#### Application



#### Stability of the tool



#### Tools



#### Designation

G1111

G1511  
G1511-P

#### Max. cutting depth $T_{max}$ [mm]

6

••

••

12

••

15

••

21

••

25

•

#### Insert width s [mm]

3.0–6.0

2.0–6.0

#### Smallest $D_{min}$ [mm]

34

43

#### Shank height h [mm]

25


12–25

#### Walter Capto™ size $d_1$

–

–


#### Cutting insert type



GX...E

GX...F

 -P = Precision cooling



			-
G1521	C...-NCEE (0°) C...-NCFE (0°) C...-NCHE (90°) C...-NCOE (90°)	NCEE (0°) NCFE (0°) NCHE (90°) NCOE (90°)	
••	••	••	
	••	••	
	••	••	
	••	••	
2.0–6.0		3.0–6.0	
43	50	50	
16–25	–	20–32	
–	C3–C6	–	
		GX...E	
		GX...F	

# Walter Select for cutting inserts for axial grooving

Step by step to the right cutting insert


## STEP 1

Determine the **material** to be machined.

Code letters	Machin- ing groups	Groups of the materials to be machined	
<b>P</b>	P1–P15	Steel	All types of steel and steel casting, with the exception of steel with an austenitic structure
<b>M</b>	M1–M3	Stainless steel	Austenitic stainless steel, austenitic-ferritic steel and steel casting
<b>K</b>	K1–K7	Cast iron	Grey cast iron, cast iron with spheroidal graphite, malleable cast iron, cast iron with vermicular graphite
<b>N</b>	N1–N10	NF metals	Aluminium and other non-ferrous metals, non-ferrous materials
<b>S</b>	S1–S10	High-temperature alloys and titanium alloys	Heat-resistant special alloys based on iron, nickel and cobalt, titanium and titanium alloys
<b>H</b>	H1–H4	Hard materials	Hardened steel, hardened cast iron materials, chilled cast iron
<b>O</b>	O1–O6	Other	Plastics, glass and carbon-fibre, reinforced plastics, graphite

## STEP 2


Determine the **basic shape** of the cutting insert:





### STEP 3 – AXIAL RECESSING

Determine the **cutting insert geometry** via the cutting edge stability and feed.



### STEP 4 – AXIAL RECESSING

Check whether your chosen geometry is available in the required insert width [s]. Identify the available system.


Chip formation		
Insert width s [mm]		
UF8	1.7–8.0	–
UD6	2.0–6.0	–
UF4	2.0–8.0	–
UD4	2.0–8.0	–
UA4	2.0–6.0	–
F1 <sup>1)</sup>	–	2.0–6.0

<sup>1)</sup> PCD cutting insert



### STEP 3 – AXIAL GROOVING

Determine the **cutting insert geometry** via the cutting edge stability and feed.



### STEP 4 – AXIAL GROOVING

Check whether your chosen geometry is available in the required insert width [s]. Identify the available system.


Chip formation		
Insert width s [mm]		
GD8	1.0-1.4	-
GD3	2.0-6.0	-
GD6	2.0-6.0	-
CE4	2.0-6.0	3.0-4.0
UF4	2.0-8.0	-
UD4	2.0-8.0	-
F1 <sup>1)</sup>	-	2.0-6.0

<sup>1)</sup> PCD cutting insert



## STEP 3 – AXIAL COPY TURNING

Determine the **cutting insert geometry** via the cutting edge stability and feed.



## STEP 4 – AXIAL COPY TURNING

Check whether your chosen geometry is available in the required insert width [s]. Identify the available system.


Chip formation		
Insert width s [mm]		
RK8	6.0–8.0	–
RF8	2.0–8.0	–
RD4	2.0–8.0	–
M1 <sup>1)</sup>	–	2.0–8.0

<sup>1)</sup> PCD cutting insert

### Axial grooving operations require specific tools


- The tool curvature of the groove turning holder depends on the workpiece radius
- When choosing the tool, take into account the inner and outer diameter of the groove
- Select the largest possible diameter range for the first groove

Standard variant




Right-hand axial tool  
Shank design 0°  
Tool curvature: External position

Standard variant




Left-hand axial tool  
Shank design 0°  
Tool curvature: External position

Contra variant



Right-hand axial tool  
Shank design 0°  
Tool curvature: Internal position


Contra variant




Left-hand axial tool  
Shank design 0°  
Tool curvature: Internal position

#### Important:

- The larger the diameter range of the first groove, the better the chip evacuation
- If possible, always begin at the outer diameter ① and work inwards ②




Standard variant




Right-hand axial tool  
Shank design 90°  
Tool curvature: External position

Standard variant




Left-hand axial tool  
Shank design 90°  
Tool curvature: External position

Contra variant



Right-hand axial tool  
Shank design 90°  
Tool curvature: Internal position

Contra variant



Left-hand axial tool  
Shank design 90°  
Tool curvature: Internal position

#### Application information:

Diameter range when using the G1511 / G1521 tools for axial grooving


#### Diameter range

Grooving insert width s [mm]	Minimum axially cut groove D <sub>min</sub> [mm]	
	GX16 D <sub>min</sub>	GX24 D <sub>min</sub>
2	112	120
2.5	92	240
3	81	65
4	75	62
5	63	51
6	53	43

## Application information

### The tool must be aligned 90° to the axis of rotation!


Firstly check the parallelism of the cutting edge and the surface to be machined. Exact positioning enables good surface finish quality when facing in both directions.



### Tool selection


According to the required machining depth:

Choose a short cutting depth  $T_{\max}$ .  
→ This minimises the risk of vibration




### Machining sequence – Roughing

- The first groove ① must always be carried out at the largest diameter
- The cutting action ② and ③ should be 0.5–0.8 times the width of the cutting insert
- Material removal at the flanks and at the bottom: At least the size of the corner radius




### Machining sequence – Finishing



- Start the first finishing cut ① in the specified diameter range directly after the radius
- In cut ②, the outer diameter is finished: Work inwards – until the end of the second radius of the inner diameter
- Finally, carry out cut ③: Finishing of the inner diameter and radius

### Deep grooving


With large cutting depths, difficult materials or poor chip breaking, step-by-step grooving is recommended in order to enable chip clearance.



### Rule of thumb

The larger the diameter range of the first groove:


- The better the chip evacuation
- The higher the tool stability (see course of the lines of force)



### Correct usage

**If the tool body of the workpiece is wearing against the component:**

- Check the diameter range of the tool
- The tool is possibly not parallel to the axis
- Check the centre height



**When approaching the inner diameter:**

- Slightly lower the tool to under the centre height

**When approaching the outer diameter:**

- Place the tool slightly over the centre height

## Cooling via the top clamp

### Walter Cut GX – G1221-P boring bar


- Precision cooling for high process reliability and long tool life
- Sealable axial coolant bore for blind-hole machining
- Interface between basic adaptor and tool, free from pressure loss thanks to O-ring seal
- Unique chip flushing effect due to the axial coolant bore for blind-hole machining



### THE TECHNOLOGY



Stable tool body design with optimal  $L \times D$  ratio



Smallest  $D_{min}$  with maximum  $T_{max}$


## THE APPLICATION

- Internal grooving and recessing to a cutting depth of up to 12 mm
- From  $D_{min} = 16$  mm
- Optimal for blind-hole machining

## APPLICATION EXAMPLE


### Internal grooving in stainless steel – Valve housing

Material:	X2CrNiMo17-12-2 (1.4404)
Tool:	G1221-40SR-5T12-GX24-P
Indexable insert:	GX24-3E500N25-RF8
Grade:	WSM23S



Cutting data:	Competitors Special tool N151.2-500-40-5P GC235	Walter G1221-40SR-5T12-GX24-P GX24-3E500N25-RF8 WSM23S
$v_c$ [m/min]	180	180
$f$ [mm]	0.33	0.33
Insert width [mm]	5.00 (R2.5)	5.00 (R2.5)
Cutting depth [mm]	1.0–3.0	1.0–3.0
Tool life quantity [units]	30	50


### Comparison: Tool life quantity [units]



## Walter Select – Groove turning holder for internal grooving and recessing

### Internal turning – Radial


#### Application



#### Stability of the tool



#### Tools



#### Designation


$D_{min}$ [mm]	Max. cutting depth $T_{max}$ [mm]	G1221-P	I12
dia. 16	3	••	••
dia. 16	4	••	
dia. 20	4	••	
dia. 20	6	••	
dia. 25	5	••	
dia. 25	8	••	
dia. 32	6	••	
dia. 32	10	••	
dia. 40	9	••	
dia. 50	10/12	••	
dia. 60	19		

Width of indexable inserts	1.7–6.0	2.0–2.5
----------------------------	---------	---------

Shank diameter $d_1$ [mm]	16–40	16
---------------------------	-------	----

Type of indexable insert	GX09/16/24	GX09
--------------------------	------------	------

-P = Precision cooling (first choice)



1.5 × D



NCAI

2.5 × D



NCCI

••

••

••

••

••

••

••

••

••

1.7-6.0

1.0-2.3

20-50

20-50



GX09/GX16/GX24

# Walter Select for cutting inserts for internal grooving and recessing

Step by step to the right cutting insert


## STEP 1

Determine the **material** to be machined.

Code letters	Machining groups	Groups of the materials to be machined	
<b>P</b>	P1–P15	Steel	All types of steel and steel casting, with the exception of steel with an austenitic structure
<b>M</b>	M1–M3	Stainless steel	Austenitic stainless steel, austenitic-ferritic steel and steel casting
<b>K</b>	K1–K7	Cast iron	Grey cast iron, cast iron with spheroidal graphite, malleable cast iron, cast iron with vermicular graphite
<b>N</b>	N1–N10	NF metals	Aluminium and other non-ferrous metals, non-ferrous materials
<b>S</b>	S1–S10	High-temperature alloys and titanium alloys	Heat-resistant special alloys based on iron, nickel and cobalt, titanium and titanium alloys
<b>H</b>	H1–H4	Hard materials	Hardened steel, hardened cast iron materials, chilled cast iron
<b>O</b>	O1–O6	Other	Plastics, glass and carbon-fibre, reinforced plastics, graphite

## STEP 2


Determine the **basic shape** of the cutting insert:





### STEP 3 – INTERNAL RECESSING

Determine the **cutting insert geometry** via the cutting edge stability and feed.



### STEP 4 – INTERNAL RECESSING

Check whether your chosen geometry is available in the required insert width [s]. Identify the available system.


Chip formation		
Insert width s [mm]		
UF8	1.7–6.0	–
UD6	2.0–6.0	–
UF4	2.0–6.0	–
UD4	2.0–6.0	–
UA4	2.0–6.0	–
F1 <sup>1)</sup>	–	2.0–6.0

<sup>1)</sup> PCD cutting insert



## STEP 3 – INTERNAL GROOVING

Determine the **cutting insert geometry** via the cutting edge stability and feed.



## STEP 4 – INTERNAL GROOVING

Check whether your chosen geometry is available in the required insert width [s]. Identify the available system.


Chip formation		
Insert width s [mm]		
GD8	1.0–1.4	–
GD3	2.0–6.0	–
GD6	2.0–6.0	–
CE4	2.0–6.0	3.0–4.0
UF4	2.0–8.0	–
UD4	2.0–8.0	–
F1 <sup>1)</sup>	–	2.0–6.0

<sup>1)</sup> PCD cutting insert



### STEP 3 – INTERNAL COPY TURNING

Determine the **cutting insert geometry** via the cutting edge stability and feed.



### STEP 4 – INTERNAL COPY TURNING

Check whether your chosen geometry is available in the required insert width [s]. Identify the available system.

Chip formation		
Insert width s [mm]		
RK8	6.0–8.0	–
RF8	2.0–8.0	–
RD4	2.0–8.0	–
M1 <sup>1)</sup>	–	2.0–8.0


<sup>1)</sup> PCD cutting insert

## Application information

### Machining sequence – Internal grooving

When internal grooving deep grooves, multiple grooving can be used as a strategy for better chip control.

### Producing a wide groove via multiple grooving




$s$  = cutting edge width /  $r$  = corner radius /  $a_p \text{ max}$  = max. depth of cut

---

### Internal recessing


In order to ensure that chips are directed outwards, when recessing long grooves (in contrast to external recessing), it is important to always work towards the entrance of the bore.

## Machining sequence – Roughing




If the chip formation allows, conventional recessing can also be used as an alternative.

## Machining sequence – Finishing




- Start the first finishing cut ① directly after the radius
- In the second cut ②, the left flank is finished
- In the third cut ③, turn in the "Z"+ direction, until the end of the second radius of the right flank
- Finally, carry out cut ④: Finishing of the right flank and radius

## Correct use of G1221-P



Coolant can exit along the boring bar because the seal in the clamping unit is open.



Coolant cannot escape because the seal in the clamping unit is closed.

## Precision cooling system overview

VDI adaptors  
for square shanks

A2120-VDI-P



A2121-VDI-P



Walter Capto™ adaptors  
for square shanks

A2120-C-P




A2121-C-P



One-piece shank tools

e.g. G1011...-P



e.g. G3011...-P



Machine-specific adaptors for BMT  
and Doosan machines for square  
shanks\*

A2120-DO-P



A2121-DO-P



A2120-BT-P



 -P = Precision cooling

\* Further manufacturers available upon request.



VDI adaptors  
for parting blades

A2110...-P



A2111...-P



Clamping blocks  
for parting blades

SBN



G2661...-P



Neutral  
parting blades

e.g. G2042...-P



Reinforced  
parting blades

e.g. G1041...-P



Machine-specific adaptors for BMT,  
Doosan and Nakamura machines  
for parting blades\*

A2110-BT...-P



A2110-DO...-P



A2110-NA...-P



## Range of applications with VDI double serrations

### A2110-P blade adaptors – Star turrets



A2110...32R...P



A2110...32R...P  
Overhead installation position



A2110...32L...P



A2110...32L...P  
Overhead installation position

### A2110-P square shank adaptors – Star turrets



A2120...25N...P



A2120...25N...P  
Overhead installation position

### A2121-P square shank adaptors – Disc turrets



A2121...25R...P



A2121...25L...P  
Overhead installation position



# Geometry overview of cutting inserts

## GX system: Grooving and parting off

Geometry	Remarks/ field of applications	Material groups							s [mm]	f [mm]
		P Steel	M Stainless steel	K Cast iron	N NF metals	S Materials with difficult cutting properties	H Hard materials	O Other		
CK8	<b>CK8</b> – Light to moderate feeds – Polished rake face	•	•	•	•	•			2	0.04–0.15
									2.5	0.05–0.15
									3	0.08–0.20
									4	0.10–0.22
									5	0.10–0.25
CF6	<b>CF6</b> – Extremely low burr and pip formation – For small diameters and thin-walled tubes	•	•	•	•	•		•	2	0.03–0.10
									2.5	0.03–0.12
									2.5	0.03–0.15
									3	0.04–0.20
CF5	<b>CF5</b> – Reduced burr and pip formation – For long-chipping materials	•	•	•	•	•		•	2	0.04–0.15
									2.5	0.05–0.15
									3	0.08–0.20
									4	0.10–0.22
									5	0.10–0.25
CE4	<b>CE4</b> – Stable cutting edge for maximum feeds – Very good chip constriction	•	•	•	•	•	•	•	2	0.06–0.15
									2.5	0.07–0.18
									3	0.09–0.30
									4	0.10–0.32
									5	0.12–0.35
GD8	<b>GD8</b> – For precision grooving – Light to moderate feeds	•	•	•	•	•			1	0.03–0.06
									1.5	0.03–0.09
									2	0.04–0.10
									2.5	0.04–0.14
									3	0.04–0.14
GD3	<b>GD3</b> – Light to moderate feeds – Soft cutting action	•	•	•	•	•		•	2	0.04–0.12
									2.5	0.06–0.14
									3	0.06–0.18
									4	0.10–0.20
									5	0.12–0.25
GD6	<b>GD6</b> – For long-chipping materials – Moderate machining conditions	•	•	•	•	•			2	0.04–0.12
									2.5	0.06–0.17
									3	0.08–0.18
									4	0.10–0.22
									5	0.12–0.24
F1	<b>F1</b> – Light to moderate feeds – PCD tipped								2	0.04–0.12
									3	0.05–0.16
									4	0.06–0.22
									5	0.06–0.25
									6	0.06–0.28

## GX system: Grooving, parting off and recessing

Geometry	Remarks/ field of applications	Material groups							s [mm]	ap [mm]	f [mm]
		P Steel	M Stainless steel	K Cast iron	N NF metals	S Materials with difficult cutting properties	H Hard materials	O Other			
	<b>UF8</b> <ul style="list-style-type: none"> <li>– Chip formation with circumference fully ground, excellent chip control</li> <li>– Low to moderate feeds</li> </ul>	••	••	•	••	••			1.6	0.3-1.0	0.05-0.17
									2	0.3-1.2	0.05-0.22
									3	0.4-1.5	0.07-0.24
									4	0.3-2.2	0.07-0.30
									5	0.3-2.6	0.11-0.35
									6	0.3-3.2	0.11-0.35
									8	1.0-4.2	0.13-0.40
	<b>UD6</b> <ul style="list-style-type: none"> <li>– Moderate feeds</li> <li>– Soft cutting action</li> </ul>	•	••		•				2	0.3-2.5	0.06-0.15
									2.5	0.3-2.5	0.08-0.14
									3	0.4-3.0	0.10-0.20
									4	0.5-3.5	0.12-0.25
									5	0.5-3.0	0.12-0.30
									6	0.6-3.5	0.14-0.35
	<b>UF4</b> <ul style="list-style-type: none"> <li>– Moderate feeds</li> <li>– Universal insert for 80% of all applications</li> </ul>	••	••	••	•	•			2	0.3-2.5	0.10-0.15
									2.5	0.3-2.5	0.10-0.18
									3	0.4-3.0	0.10-0.20
									4	0.5-3.5	0.10-0.30
									5	0.5-3.5	0.12-0.35
									6	0.6-4.0	0.14-0.40
									8	0.9-4.0	0.18-0.55
	<b>UD4</b> <ul style="list-style-type: none"> <li>– Excellent chip breaking with forged parts</li> <li>– Stable cutting edge</li> </ul>	••	•	••					3	0.4-2.0	0.08-0.20
									4	0.5-2.8	0.10-0.30
									5	0.5-3.0	0.12-0.35
									6	0.6-3.5	0.14-0.40
									8	0.9-4.0	0.14-0.40
	<b>UA4</b> <ul style="list-style-type: none"> <li>– For machining cast iron</li> <li>– Moderate to high feeds</li> </ul>		••		••		•		2	0.3-2.5	0.08-0.15
									2.5	0.3-2.5	0.10-0.20
									3	0.4-3.0	0.10-0.22
									4	0.5-3.5	0.10-0.35
									5	0.5-3.0	0.12-0.35
									6	0.6-3.5	0.14-0.40
	<b>VG7</b> <ul style="list-style-type: none"> <li>– For finishing operations behind the collar of a component</li> <li>– Enormous savings on material possible</li> </ul>	••	••	•	••	••			2.8	0.2-2.5	0.05-0.25

•• Primary application  
• Additional application

## Geometry overview of cutting inserts

**GX system: Full radius cutting inserts for grooving and copy turning**

Geometry	Remarks/ field of applications	Material groups							s [mm]	a <sub>p</sub> [mm]	f [mm]
		P Steel	M Stainless steel	K Cast iron	N NF metals	S Materials with difficult cutting properties	H Hard materials	O Other			
 RK8	<ul style="list-style-type: none"> <li>For copy and relief turning of ISO N materials</li> <li>Polished cutting edge with circumference fully ground</li> </ul>	•		•	••			•	6	4.0	0.10–0.30
									8	5.0	0.10–0.35
 RF8	<ul style="list-style-type: none"> <li>For copy and relief turning</li> <li>Reduced cutting forces due to positive cutting edge with circumference fully ground</li> </ul>	••	••	•	•	••			2	0.1–1.0	0.08–0.25
									3	0.1–1.5	0.10–0.30
									4	0.1–2.0	0.12–0.45
									5	0.1–2.5	0.15–0.50
									6	0.1–3.0	0.15–0.55
									8	0.2–4.0	0.18–0.60
 RD4	<ul style="list-style-type: none"> <li>For copy turning, e.g. of forged parts</li> <li>Excellent chip control even at low depths of cut</li> </ul>	••	•	••	•	•			2	0.2–1.0	0.08–0.25
									3	0.5–1.5	0.10–0.35
									4	0.5–2.0	0.15–0.50
									5	0.5–2.5	0.17–0.70
									6	0.5–3.0	0.17–0.70
									8	0.6–4.5	0.17–0.70
 M1	<ul style="list-style-type: none"> <li>For copy and relief turning</li> <li>Stable cutting edge</li> <li>PCD tipped</li> </ul>	•		•	••	•			2	0.1–1.0	0.05–0.25
									3	0.1–1.5	0.05–0.30
									4	0.1–2.0	0.05–0.35
									5	0.1–2.5	0.05–0.40
									6	0.2–3.0	0.05–0.50
									8	0.2–4.0	0.05–0.60

•• Primary application

• Additional application

## MX system: Cutting inserts for grooving, parting off, recessing and thread turning

Geometry	Remarks/ field of applications	Material groups							s [mm]	a <sub>p</sub> [mm]	f [mm]
		P Steel	M Stainless steel	K Cast iron	N NF metals	S Materials with difficult cutting properties	H Hard materials	O Other			
	<b>GD8</b> <ul style="list-style-type: none"><li>- Circumference fully ground for precision grooves, e.g. DIN 471 circlip grooves</li><li>- Extremely soft cutting action</li></ul>	••	•	•	•	•			1		0.03–0.06
									1.5		0.03–0.09
									2		0.04–0.10
									2.5		0.04–0.14
									3		0.04–0.14
	<b>CF5</b> <ul style="list-style-type: none"><li>- Excellent chip control, e.g. even with long-chipping materials</li><li>- Low burr/centre pip formation</li></ul>	••	••	•	•	••			1		0.03–0.07
									1.5		0.03–0.10
									2		0.04–0.14
									2.5		0.04–0.16
									3		0.04–0.16
									4		0.10–0.22
									5		0.10–0.25
	<b>RF5</b> <ul style="list-style-type: none"><li>- Circumference fully ground for full radius grooves and for copy turning</li><li>- For low to moderate feeds</li></ul>	••	••	•	•	••			2		0.04–0.14
									2.5		0.04–0.18
									3		0.04–0.20
									4		0.06–0.22
									5		0.06–0.25
	<b>AG60</b> <ul style="list-style-type: none"><li>- 60° partial profile external thread</li><li>- Pitch range 0.5–3.0 mm</li></ul>	••	••	•	•	••			3.35		–
									5.65		–
	<b>VG8</b> <ul style="list-style-type: none"><li>- For finishing operations behind the collar of a component</li><li>- Enormous savings on material compared to standard ISO indexable inserts</li></ul>	••	••	•	••	••			2.8	0.2–2.5	0.05–0.25

Additional shapes via Walter Xpress

•• Primary application  
• Additional application

## Geometry overview of cutting inserts

### SX system: Grooving and parting off

Geometry	Remarks/ field of applications	Material groups							s [mm]	f [mm]
		P Steel	M Stainless steel	K Cast iron	N NF metals	S Materials with difficult cutting properties	H Hard materials	O Other		
	<b>CK8</b> – Light to moderate feeds – Polished rake face				••	•			2 2.5 3 4 5	0.04–0.15 0.05–0.15 0.08–0.20 0.10–0.22 0.10–0.25
	<b>CF6</b> – Low burr/centre pip formation – Low cutting force	••	••		••	••		•	1.5 2 3	0.03–0.10 0.03–0.12 0.04–0.20
	<b>CF5</b> – Good chip control, e.g. even with long-chipping materials – Minimal burr and pip formation	••	••	•	••	••		•	1.5 2 3 4 5 6	0.03–0.13 0.04–0.15 0.08–0.20 0.10–0.20 0.10–0.25 0.12–0.28
	<b>CE4</b> – Good chip constriction – Stable cutting edge for maximum feeds	••	•	••	•	•	•	•	1.5 2 3 4 5 6 8 10	0.05–0.13 0.06–0.15 0.09–0.30 0.10–0.32 0.12–0.35 0.12–0.40 0.20–0.50 0.25–0.55
	<b>UF4</b> – Moderate feeds – Universal inserts for recessing	••	••	••	•	•			8	0.18–0.55

•• Primary application  
• Additional application

## UX system: Grooving and widening

Geometry	Remarks/ field of applications	Material groups							s [mm]	f [mm]
		P Steel	M Stainless steel	K Cast iron	N NF metals	S Materials with difficult cutting properties	H Hard materials	O Other		
	<b>GD2</b> <ul style="list-style-type: none"> <li>- Universal chip formation</li> <li>- For grooving and widening wide grooves</li> <li>- Very short chips</li> <li>- Low to high feeds</li> </ul>	••		••					12	0.20–0.40
									19	0.25–0.60

•• Primary application

• Additional application

## Cutting tool material application chart – Grooving

## Carbide

Walter grade designation	Standard designation	Steel	Material groups					
			P	M	K	N	S	H
WSM13S	HC – M 10		••					
	HC – S 10						••	
	HC – P 10	•						
WSM23S	HC – M 20		••					
	HC – S 20						••	
	HC – P 20	••						
WSM33S	HC – S 30						••	
	HC – M 30		••					
	HC – P 30	••						
WSM43S	HC – S 45						••	
	HC – M 45		••					
	HC – P 45	••						
WKP13S	HC – P 10	••						
	HC – K 20			••				
	HC – H 10							•
WKP23S	HC – P 20	••						
	HC – K 25			••				
WKP33S	HC – P 30	••						
	HC – K 30			••				
WK1	HW – N 10				••			
	HW – S 10					•		
WDN10	DP – N 10	••			••			

HC = Coated carbide  
 HW = Uncoated carbide  
 DP = Polycrystalline diamond

•• Primary application  
 • Additional application

Range of applications								Coating method	Coating composition	Indexable insert example
01	05	10	15	20	25	30	35			
								PVD	TiAlN + Al <sub>2</sub> O <sub>3</sub> (Al)	
								PVD	TiAlN + Al <sub>2</sub> O <sub>3</sub> (Al)	
								PVD	TiAlN + Al <sub>2</sub> O <sub>3</sub> (Al)	
								PVD	TiAlN + Al <sub>2</sub> O <sub>3</sub> (Al)	
								CVD	TiCN + Al <sub>2</sub> O <sub>3</sub> (+ TiCN)	
								CVD	TiCN + Al <sub>2</sub> O <sub>3</sub> (+ TiCN)	
								CVD	TiCN + Al <sub>2</sub> O <sub>3</sub> (+ TiCN)	
								-	-	
								PCD	-	

## Cutting data – Grooving and recessing

Material group	Overview of the main material groups and code letters				Brinell hardness HB	Tensile strength $R_m$ N/mm <sup>2</sup>	Machining group	Symbol
P	Non-alloyed steel	C ≤ 0.25%	Annealed	125	430	P1	•••	•
		C > 0.25 to ≤ 0.55%	Annealed	190	640	P2	•••	•
		C > 0.25 to ≤ 0.55%	Heat-treated	210	710	P3	•••	•
		C > 0.55%	Annealed	190	640	P4	•••	•
		C > 0.55%	Heat-treated	300	1010	P5	•••	•
	Free-machining steel (short-chipping)	Annealed	220	750	P6	•••	•	
M	Low-alloyed steel	Annealed		175	590	P7	•••	•
		Heat-treated		285	960	P8	•••	•
		Heat-treated		380	1280	P9	•••	•
		Heat-treated		430	1480	P10	•••	•
	High-alloyed steel and high-alloyed tool steel	Annealed		200	680	P11	•••	•
		Hardened and tempered		300	1010	P12	•••	•
K	Stainless steel	Hardened and tempered		380	1280	P13	•••	•
		Ferritic/martensitic, annealed		200	680	P14	•••	•
	GGV (CGI)	Martensitic, heat-treated		330	1110	P15	•••	•
		Austenitic, quench hardened		200	680	M1	•••	•
N	Stainless steel	Austenitic, precipitation hardened (PH)		300	1010	M2	•••	•
		Austenitic/ferritic, duplex		230	780	M3	•••	•
		Ferritic		200	400	K1	•••	•
K	Malleable cast iron	Pearlitic		260	700	K2	•••	•
		Low tensile strength		180	200	K3	•••	•
	Grey cast iron	High tensile strength/austenitic		245	350	K4	•••	•
		Ferritic		155	400	K5	•••	•
S	Cast iron with spheroidal graphite	Pearlitic		265	700	K6	•••	•
		GGV (CGI)		230	400	K7	•••	•
	Wrought aluminium alloys	Not hardenable		30	–	N1	•••	•
		Hardenable, hardened		100	340	N2	•••	•
	Cast aluminium alloys	≤ 12% Si, not hardenable		75	260	N3	•••	•
		≤ 12% Si, hardenable, hardened		90	310	N4	•••	•
		> 12% Si, not hardenable		130	450	N5		
O	Magnesium-based alloys			70	250	N6		
		Unalloyed, electrolytic copper		100	340	N7	•••	•
	Copper and copper alloys (bronze/brass)	Brass, bronze, red brass		90	310	N8	•••	•
		Cu alloys, short-chipping		110	380	N9	•••	•
		High tensile, Ampco		300	1010	N10		
S	Heat-resistant alloys	Fe-based	Annealed	200	680	S1	•••	•
			Hardened	280	940	S2	•••	•
		Ni- or Co-based	Annealed	250	840	S3	•••	•
			Hardened	350	1180	S4	•••	•
			Cast	320	1080	S5	•••	•
T	Titanium alloys	Pure titanium		200	680	S6	•••	•
		$\alpha$ and $\beta$ alloys, hardened		375	1260	S7	•••	•
		$\beta$ alloys		410	1400	S8	•••	•
	Thermoplastics	Without abrasive fillers				01	•••	
	Thermosets	Without abrasive fillers				02	•••	
P	Plastics	Glass-fibre-reinforced, GFRP				03	•••	
		Glass-fibre-reinforced, CFRP				04	•••	
		Aramid-fibre-reinforced, AFRP				05	•••	
		Graphite (technical)				06	•••	

## Note:

The cutting data indicates standard values.  
Adjustment in individual cases is recommended.  
Dry machining reduces tool life on average by 20–30%.

	Cutting material grades							
	Starting values for cutting speed $v_c$ [m/min]							
	WSM13S ↔	WSM23S ↔	WSM33S ↔	WSM43S ↔	HC WKP13S ↔	WKP23S ↔	WKP33S ↔	DP WDN10 ↔
200	190	180	170	220	200	180		
180	170	170	160	200	180	170		
170	160	150	140	190	170	160		
190	180	170	160	200	180	170		
160	150	140	130	170	150	150		
190	180	170	160	200	180	170		
190	180	160	150	200	180	160		
160	150	110	100	170	150	150		
160	150	100	100	170	150	130		
				100	80	60		
140	130	120	110	180	170	160		
120	110	90	80	160	150	140		
				100	80	60		
190	180	160	140	200	180	160		
120	100	80	60	130	120	110		
190	170	150	130					
120	100	80	60	130	120	110		
170	150	130	110					
190	180	170		190	160	140		
170	160	150		170	130	100		
220	210	200		350	330	250		
180	170	160		310	300	290		
220	210	200		300	290	280		
180	170	160		260	250	240		
				220	200	180		
							2800	
							1800	
							2000	
							1600	
							550	
							1600	
							900	
							850	
							550	
							300	
110	100	90	80					
60	50	40	30					
90	80	70	60					
80	70	60	50					
80	70	60	50					
160	150	130	120				220	
45	40	35	30				180	
35	30	25					160	
							1200	
							1200	
							900	
							700	
							700	
							300	

HC = Coated carbide

DP = Polycrystalline diamond

## Cutting data – Parting off

Material group	Overview of the main material groups and code letters				Brinell hardness HB	Tensile strength $R_m$ N/mm <sup>2</sup>	Machining group	Icon
P	Non-alloyed steel	C ≤ 0.25%	Annealed	125	430	P1	•••	•
		C > 0.25 to ≤ 0.55%	Annealed	190	640	P2	•••	•
		C > 0.25 to ≤ 0.55%	Heat-treated	210	710	P3	•••	•
		C > 0.55%	Annealed	190	640	P4	•••	•
		C > 0.55%	Heat-treated	300	1010	P5	•••	•
	Free-machining steel (short-chipping)	Annealed	220	750	P6	•••	•	
M	Low-alloyed steel	Annealed	175	590	P7	•••	•	
		Heat-treated	285	960	P8	•••	•	
		Heat-treated	380	1280	P9	•••	•	
		Heat-treated	430	1480	P10	•••	•	
	High-alloyed steel and high-alloyed tool steel	Annealed	200	680	P11	•••	•	
		Hardened and tempered	300	1010	P12	•••	•	
K	Stainless steel	Hardened and tempered	380	1280	P13	•••	•	
		Ferritic/martensitic, annealed	200	680	P14	•••	•	
	GGV (CGI)	Martensitic, heat-treated	330	1110	P15	•••	•	
		Austenitic, quench hardened	200	680	M1	•••	•	
N	Stainless steel	Austenitic, precipitation hardened (PH)	300	1010	M2	•••	•	
		Austenitic/ferritic, duplex	230	780	M3	•••	•	
		Ferritic	200	400	K1	•••	•	
K	Malleable cast iron	Pearlitic	260	700	K2	•••	•	
		Low tensile strength	180	200	K3	•••	•	
	Grey cast iron	High tensile strength/austenitic	245	350	K4	•••	•	
		Ferritic	155	400	K5	•••	•	
N	Cast iron with spheroidal graphite	Pearlitic	265	700	K6	•••	•	
		GGV (CGI)	230	400	K7	•••	•	
	Wrought aluminium alloys	Not hardenable	30	–	N1	•••	•	
		Hardenable, hardened	100	340	N2	•••	•	
	Cast aluminium alloys	≤ 12% Si, not hardenable	75	260	N3	•••	•	
		≤ 12% Si, hardenable, hardened	90	310	N4	•••	•	
S	Heat-resistant alloys	> 12% Si, not hardenable	130	450	N5			
		Magnesium-based alloys	70	250	N6			
		Copper and copper alloys (bronze/brass)	Unalloyed, electrolytic copper	100	340	N7	•••	•
		Brass, bronze, red brass	90	310	N8	•••	•	
		Cu alloys, short-chipping	110	380	N9	•••	•	
O	Plastics	High tensile, Ampco	300	1010	N10			
		Fe-based	Annealed	200	680	S1	•••	•
			Hardened	280	940	S2	•••	•
		Ni- or Co-based	Annealed	250	840	S3	•••	•
			Hardened	350	1180	S4	•••	•
T	Titanium alloys		Cast	320	1080	S5	•••	•
		Pure titanium		200	680	S6	•••	•
		$\alpha$ and $\beta$ alloys, hardened		375	1260	S7	•••	•
	Thermoplastics	$\beta$ alloys		410	1400	S8	•••	•
		Without abrasive fillers				01	•••	
		Without abrasive fillers				02	•••	
P	Plastics	Glass-fibre-reinforced, GFRP				03	•••	
		Glass-fibre-reinforced, CFRP				04	•••	
		Aramid-fibre-reinforced, AFRP				05	•••	
		Graphite (technical)				06	•••	

## Note:

The cutting data indicates standard values.  
Adjustment in individual cases is recommended.  
Dry machining reduces tool life on average by 20–30%.

	Cutting material grades						
	Starting values for cutting speed $v_c$ [m/min]						
	WSM13S ↑	WSM23S ↑	HC WSM33S ↑	WSM43S ↑	WKP23S ↑	HW WK1 ↑	DP WDN10 ↑
190	180	170	160	190			
180	170	160	150	170			
160	150	140	130	160			
180	170	160	150	170			
150	140	130	120	140			
180	170	160	150	170			
180	170	150	140	170			
150	140	100	90	140			
150	140	90	90	140			
130	120	110	100	120			
110	100	80	70	100			
180	170	150	130				
100	90	70	50				
170	160	140	120				
100	90	70	50				
150	140	120	100				
180	170	160		180			
160	150	140		160			
230	220	210		230			
190	180	170		190			
210	200	190		210			
170	160	150		170			
				190			
					900	2800	
					600	1800	
					350	2000	
					250	1600	
						550	
						1600	
						400	900
						300	850
						200	550
							300
100	90	80	70				
50	40	30	25				
80	70	60	50				
70	60	50	40				
70	60	50	40				
150	140	130	110				220
50	40	30	25				180
40	30	25					160
							1200
							1200
							900
							700
							700
							300

HC = Coated carbide HW = Uncoated carbide DP = Polycrystalline diamond

## Wear analysis and counter-measures



**Flank face wear** is caused by abrasion between the workpiece and the tool at the flank face of the indexable insert.

### Measures

1. Reduce the cutting speed
2. Use a more wear-resistant cutting tool material
3. Increase the feed
4. Increase the coolant pressure/ check the alignment



**Crater wear** is caused by diffusion and abrasion on the rake face.

### Measures

1. Reduce the cutting speed
2. Use a more wear-resistant cutting tool material
3. Reduce the feed
4. Use a geometry with a greater rake angle
5. Increase the coolant pressure/ check the alignment



**Micro galling** causes parts of the workpiece material to stick to the cutting edge, resulting in a build-up on the cutting edge.

### Measures

1. Increase/reduce the cutting speed
2. Use an indexable insert with a sharper cutting edge
3. Use a cutting tool material with a treated (smoother) surface
4. Increase the coolant pressure/ check the alignment



**Fractures** are caused by vibration, interrupted cuts, chip impacts and thermal shocks in combination with cutting tool material substrates that are too hard.

### Measures

1. Reduce the cutting speed
2. Use a tougher cutting tool material
3. Reduce the feed
4. Check the tool stability if vibration occurs
5. Use more stable geometry
6. Use screw clamping instead of a self-clamping system



**Plastic deformation** is caused by excessive heat development combined with excessive mechanical stress.

#### Measures

1. Use a more wear-resistant cutting tool material
2. Reduce the feed
3. Reduce the depth of cut
4. Reduce the cutting speed
5. Increase the coolant pressure/  
check the alignment



**Notch wear** often occurs during the machining of workpieces with a hard surface (forged or cast).

#### Measures

1. Reduce the cutting speed
2. Reduce the feed
3. Use a more wear-resistant cutting tool material
4. Use a less sharp indexable insert
5. Vary the depth of cut
6. Increase the coolant pressure/  
check the alignment



**Thermal cracks** are caused by fluctuations in temperature (thermal shock).

#### Measures

1. Reduce the cutting speed
2. Reduce the feed
3. Use a tougher cutting tool material
4. Use a less sharp indexable insert
5. Turn off the coolant supply when machining interrupted cuts

## Hardness comparison table

### Tensile strength, Brinell, Vickers and Rockwell hardness (extract from DIN 50150)

Tensile strength Rm N/mm <sup>2</sup>	Vickers hardness HV	Brinell hardness HB	Rockwell hardness HRC
255	80	76.0	
320	100	95.0	
385	120	114	
450	140	133	
510	160	152	
575	180	171	
640	200	190	
705	220	209	
770	240	228	20.3
835	260	247	24.0
900	280	266	27.1
965	300	285	29.8
1030	320	304	32.2
1095	340	323	34.4
1155	360	342	36.6
1220	380	361	38.8
1290	400	380	40.8
1350	420	399	42.7
1420	440	418	44.5
1485	460	437	46.1
1555	480	(456)	47.7
1630	500	(475)	49.1
1700	520	(494)	50.5
1775	540	(513)	51.7
1845	560	(532)	53.0
1920	580	(551)	54.1
1995	600	(570)	55.2
2070	620	(589)	56.3
2145	640	(608)	57.3
	660		58.3

Any hardness values converted on the basis of this table will be approximate only.

See DIN 50150.


Material property	Unit/ test method	Symbol
Tensile strength	N/mm <sup>2</sup>	R <sub>m</sub>
Vickers hardness	Diamond pyramid 136° Testing force F ≥ 98 N	HV
Brinell hardness Calculated from: HB = 0.95 × HV	0.102 × F/D <sup>2</sup> = 30 N/mm <sup>2</sup> F = testing force in N D = sphere diameter in mm	HB
Rockwell hardness C	Diamond cone 120° Overall testing force 1471 ± 9 N	HRC



# Walter AG

Derendinger Straße 53, 72072 Tübingen  
Postfach 2049, 72010 Tübingen  
Germany

[walter-tools.com](http://walter-tools.com)



## Walter GB Ltd.

Bromsgrove, England  
+44 (1527) 839 450, [service.uk@walter-tools.com](mailto:service.uk@walter-tools.com)

## Walter Kesici Takımlar Sanayi ve Ticaret Ltd. Şti.

Istanbul, Türkiye  
+90 (0) 216 528 1900 Pbx, [service.tr@walter-tools.com](mailto:service.tr@walter-tools.com)

## Walter Wuxi Co. Ltd.

Wuxi, Jiangsu, P.R. China  
+86 (510) 853 72199, [service.cn@walter-tools.com](mailto:service.cn@walter-tools.com)

## Walter AG Singapore Pte. Ltd.

+65 6773 6180, [service.sg@walter-tools.com](mailto:service.sg@walter-tools.com)

## Walter Korea Ltd.

Anyang-si Gyeonggi-do, Korea  
+82 (31) 337 6100, [service.kr@walter-tools.com](mailto:service.kr@walter-tools.com)

## Walter Tools India Pvt. Ltd.

Pune, India  
+91 (20) 3045 7300, [service.in@walter-tools.com](mailto:service.in@walter-tools.com)

## Walter (Thailand) Co., Ltd.

Bangkok, 10120, Thailand  
+66 2 687 0388, [service.th@walter-tools.com](mailto:service.th@walter-tools.com)

## Walter Malaysia Sdn. Bhd.

Selangor D.E., Malaysia  
+60 (3) 8023 7748, [service.my@walter-tools.com](mailto:service.my@walter-tools.com)

## Walter Japan K.K.

Nagoya, Japan  
+81 (52) 533 6135, [service.jp@walter-tools.com](mailto:service.jp@walter-tools.com)

## Walter USA, LLC

Waukesha WI, USA  
+1 800-945-5554, [service.us@walter-tools.com](mailto:service.us@walter-tools.com)

## Walter Canada

Mississauga, Canada  
[service.ca@walter-tools.com](mailto:service.ca@walter-tools.com)